



Note: R1 is not populated. If you need to boost the +5V supply, Adding about 150k ohms in R1 will boost voltage by 0.25V

Title		
<b>Gottlieb System 1 Power Supply Schematic</b>		
Size A	Document Number	Rev A
	<b>GPS002</b>	
Date:	Sunday, September 30, 2007	Sheet 1 of 1